

### MICRO P OWNERS MANUAL





### CONTENTS

1.	INTRODUCTION	2
2.	RECEIVING AND UNPACKING	3
3.	SAFETY CONSIDERATIONS	3
4.	CONNECTOR WIRING INFORMATION	4
5.	MECHANICAL ASSEMBLY	6
6.	PANEL MOUNTING	7
7.	CONNECTORS	7
8.	FRONT PANEL SETUP KEYS	8
9.	SETTING MENU LOCKOUTS	9
10.	SETUP MENU	10
11.	DC VOLTS & AMPS	20
12.	PROCESS SIGNAL INPUTS	22
13.	THERMOCOUPLES	24
14.	PT100 RTD'S	
15.	STRAIN GAUGES AND POTENTIOMETERS	
16.	TRUE RMS VOLTS & AMPS	30
17.	LOAD CELLS AND MICROVOLTMETER	
18.	DUAL ALARM OUTPUTS	
19.	ANALOG OUTPUT	
20.	RS-232 AND RS-485 INTERFACE	
21.	PARALLEL BCD OUTPUT	38
22.	10 AND 24 VDC EXCITATION OUTPUTS	39
23.	DIGITAL CONTROL INPUTS	40
24.	CALIBRATION	41
25	SPECIFICATIONS	11

### INTRODUCTION

1.

This series of panel instruments is a versatile, cost effective solution to a wide variety of monitoring and control applications. These instruments are easily set to produce an accurate display of temperature, pressure, flow, weight, voltage or current. Front panel push-button or RS-232/RS-485 setup allows the user to customize the unit for a specific application. Digital scaling of zero and span provides direct readout in engineering units. Concurrent Slope (Pat 5,262,780) is a new method of analog-to-digital conversion that provides 60 conversions per second (50 for 50 Hz operation) while integrating over a full cycle of the line for maximum noise rejection. Self calibration cycles reduce the average reading rate to 56 per second (47 for 50 Hz). This fast read rate provides an accurate display of peak signal input and quick response in control applications. The adaptive auto filter automatically supplies a time constant compatible with the signal noise level. This ensures stable displayed readings and outputs while responding rapidly to changes of the input signal that exceed a selected threshold value. Selective security lockout of the front panel setup protects against accidental changes to the meter. The instrument uses a lightweight, high-efficiency switching power supply operating from AC or DC voltages. The meter can be powered worldwide without changes to the supply. An optional low voltage supply operates on 9 to 37 Vdc from batteries or 8 to 28 Vac from sources such as 400 Hz aircraft power. Both supplies have isolated 5, 10, and 24 Vdc excitation outputs to power transducers. The NEMA 4 (IP65) 1/8 DIN case is made of high impact, 94V-0 UL-rated plastic. Mounting is from the front of the panel and requires less than 110 mm behind the panel. All wiring is by removable plugs conforming to IEC950 safety standards. All output options are isolated from meter and power ground by 250 Vac minimum.

The extended DPM is capable of linearizing a nonlinear input signal such as a thermistor, gallons of liquid in a irregularly shaped tank, or altitude. Up to 240 points may be linearized by a computer program that stores the parameters via RS232 into permanent nonvolatile memory. The meter is also capable of measuring rate of change. The level of a tank is measured and the difference between readings determines the flow rate in or out of the tank.

The dual setpoints have two form C ( 10 A @ 250 Vac ) relays or solid state relay outputs for alarm and control capabilities. Either setpoint may be latching or nonlatching and separately configured to be energized above or below the setpoint, as deviation alarms, or in a fail-safe mode. Additionally, outputs may also be selected to operate from the filtered signal to reduce relay chatter or from the unfiltered signal for fast response. Snubber circuits, programmable relay switching time delay and selectable hysteresis extend relay contact life.

Isolation of the 4 to 20 mA and 0 to +10 V analog outputs eliminates ground loop problems. The output may be scaled by front panel push-buttons or RS-232/RS-485. For thermocouples and RTD's, the output is linearized. The 4 to 20 mA output will drive up to an 600 Ohm load with 12 V compliance

The meter offers RS232 or RS485 bidirectional communications or parallel, 3-state BCD output to interface with computers, PLC's or other digital devices. IBM PC compatible software is available for programming the unit by the RS232 and RS-485 interfaces.

### 2. RECEIVING AND UNPACKING

Your meter was carefully tested and inspected prior to shipment. Should the meter be damaged in shipment, notify the freight carrier immediately. In the event the meter is not configured as ordered or the unit is inoperable, return the unit to the place of purchase for repair or replacement. Please include a detailed description of the problem.

# 3. SAFETY CONSIDERATIONS

**Warning**  $\overline{W}$ : The use of this equipment in a manner other than specified may impair the protection of the device and subject the user to a hazard.

Visually inspect the unit for signs of damage. If the unit is damaged, do not attempt to operate.

This unit must be powered with AC (mains) from 85 to 264 Vac (90 to 370 Vdc) with the high voltage power supply option or 8 to 28 Vac (9 to 37 Vdc) with the low voltage power supply option. Verify that the proper power option is installed for the power to be used.

This meter has no AC (mains) switch; it will be in operation as soon as power is connected.

**Caution:** The 85 to 264 Vac (90 to 370 Vdc) mains connector (J1 Pins 1-3) is color coded Light Blue to differentiate it from other input and output connectors. The 8 to 28 Vac (9 to 37 Vdc) mains connector is not color coded because these voltages are not considered hazardous.

Do not make signal wiring changes or connections when power is applied to the instrument. Make signal connections before power is applied and, if reconnection is required, disconnect the AC ( mains ) power before such wiring is attempted.

To prevent electrical or fire hazard, do not expose the instrument to excessive moisture.

Do not operate the instrument in the presence of flammable gases or fumes; such an environment constitutes a definite safety hazard. This meter is designed to be mounted in a metal panel.


Verify the panel cutout dimensions and mount according to instructions.

#### 4.


#### CONNECTOR WIRING INFORMATION

#### 4.1 CONNECTOR LOCATION

The connectors are the screw terminals that plug into the mating jack mounted on the printed circuit board. P3 is either a 6 conductor phone plug for RS-232 and RS-485 or a 30 pin, mass termination, edge connector for parallel BCD.



#### 4.2 J1 - POWER AND DIGITAL CONTROLS



\*Note:

Non-isolated digital control inputs


A and B are menu selectable for Tare,


Peak Display, Hold, or Reset and external control of decimal points.

Digital Input B selected - Jumper "h" +5V Output selected - Jumper "g"


#### 4.3 J5 - SIGNAL INPUT

SIGNAL HIGH






### 2 WIRE PROCESS TRANSMITTER




#### STRAIN GAUGE




LH


### RTD (2-WIRE)




#### RTD (3-WIRE)



#### RTD (4-WIRE)



#### **THERMOCOUPLE**




- AC HIGH

# 4.3 J5 - SIGNAL INPUT ( CONTINUED ) LOAD CELL METER

# -10 V EXCITATION 1 -SENSE 2 -SIGNAL 3 +SIGNAL 4 +10 V EXCITATION 5 +SENSE 6

#### 4.4 J4 - ANALOG OUTPUT




#### 4.5 J 2 - DUAL SETPOINT CONTROLLER


#### **RELAY OUTPUTS**




# SOLID STATE RELAY OUTPUTS Switching AC 125Vac @120 ma max.



# SOLID STATE RELAY OUTPUTS Switching DC 125Vdc @240 ma max.





# \* SOLID STATE RELAY OUTPUTS Switching DC 125Vdc @120 ma max.




This configuration is directly compatible with the optotransistor output board.

#### 4.6 J3 DIGITAL INTERFACE






#### BCD OUTPUT



#### **RS - 485 INTERFACE**



#### 5.1 REMOVING THE REAR PANEL

To remove the rear panel, first remove any connectors that are installed. Press down on both rear panel retaining tab releases(see Fig. 5.1) and pull the top of the rear panel away from the case. The bottom of the rear panel will now lift out.





Figure 5.1

#### 5.2 Removing the meter from the case

After removing the rear panel, the meter can be taken out of the case by carefully grasping the power supply board and signal conditioner board at the connectors and sliding the unit out the back of the case. See Figure 5.2.




#### 5.3 REASSEMBLING THE METER


Reverse the preceding procedures to reinstall the meter in the case. After the meter is in the case, insert the bottom tabs on the rear panel into the case first. Care must be taken to ensure the printed circuit boards are properly aligned by the board retaining pins on the inside of the rear panel.

### 6. PANEL MOUNTING


Ensure the O-ring is in place. Turn the two mounting screws counterclockwise until the space between the mounting pawl and the bezel is greater than the panel thickness. Insert the meter in the panel cutout. Turn the mounting screws clockwise until the meter is securely mounted in the panel. Do not overtighten the mounting screws.



The meter uses UL/VDE rated screw terminal connections that plug into the mating PC jack.



### 8. FRONT PANEL SETUP KEYS



#### **MENU KEY**

The menu key steps through the various meter parameters that may be selected. These menu items may be "locked out" from front panel selection by software and hardware.

#### PEAK DISPLAY KEY (DIGIT SELECT)

In the **Operating Mode**, pressing the Peak Display Key causes the peak value of the input signal to be displayed. Pressing the key again returns the display to the present value. In the **Menu Mode**, the Digit Select Key (Peak Display Key) is used to select input type and decimal point or to select one of the five display digits for programming. In the main menu, pressing the Digit Select Key causes the value or code that is stored for that menu item to be displayed and the left hand digit flashes. Each time the key is pressed, the next digit to the right will flash. The value of the flashing digit may be changed using the Value Select Key. In the **Alarm Mode**, pressing the Digit Select Key causes the most significant digit of the displayed setpoint value to flash. Digits are then selected the same as in the Menu Mode.

#### **RESET KEY (VALUE SELECT)**

In the **Operating Mode**, holding the Reset Key depressed and pressing any other key causes a reset to occur. The Menu Key resets all meter functions, the Alarm Key resets any alarm conditions and the Peak Display Key resets the peak value to present value. In the **Menu Mode** or **Alarm Mode**, the Value Select Key (Reset Key) sets the value of the flashing digit. Each time the key is pressed, the value increases by one. Holding the key down causes the digit to automatically step through the numbers.

### ALARM KEY (REVERSE MENU)


In the **Operating Mode**, pressing the Alarm Key displays the setpoint of Alarm 1 and then Alarm 2. These values may be changed using the Digit Select Key and the Value Select Key. In the **Menu Mode**, pressing the Alarm Key steps the display backward through the menu.

#### 9.

### **SETTING MENULOCKOUTS**

For security and ease of operation, any or all program menu items may be disabled. Each function to be disabled is set to "1" in the menu items, "Loc 1"," Loc 2" or "Loc 3". These lockout menu items may in turn be "locked-out" by installing an internal hardware shorting jumper. With the jumper installed, the operator has access only to enabled menu items.

#### 9.1 SETTING HARDWARE LOCKOUT JUMPER



Power Supply Board Figure 9.1

#### **Lockout Jumper**

To access the jumper, remove the rear panel per Section 5.1. Remove jumper "a" located on the lower portion of the power supply board next to the input connectors (see figure at left) to enable the software lockouts. Replace the jumper to disable software lockouts.

**Jumper Removed -** Loc 1,2 and 3 are displayed as menu items and allow other menu items to be locked out or enabled.

**Jumper Installed** - Loc1, 2 and 3 are not displayed on program menu

#### 9.2 SETTING SOFTWARE LOCKOUTS

When setting up the meter, it may be necessary to enable some of the menu items. Any digit set to "1" in Loc 1, Loc 2 or Loc 3 indicates that item is locked out. By setting the digit to "0", the item will appear in the menu. Be sure to reset the lockout bit to "1" after selection if you do not want the value changed by the operator.

**Note:** The hardware lockout jumper must be removed to access Loc 1, 2 and 3 (see section 9.1)

MENU KEY

DIGIT SELECT KEY

VALUE SELECT KEY▲



Press the key until Loc 1 is displayed.

Press ▶ to display status and select left digit. Press ▶ again to select another digit. Selected digit will flash. "1" indicates the menu item is disabled. "0" indicates the item is enabled.

1 2 3 4 5

Press ▲ to select "0" or "1" for flashing digit

- 1 Input type selection
- 2 Meter setup, configuration & decimal pt.
- 3 Filter selection
- 4 -Scale or Lo, Hi Input
- 5 Offset or Lo, Hi Reading

### DIGIT SELECT KEY

### **VALUE SELECT KEY**



1111

Press the key until Loc 2 is displayed.

Press ▶ to display status and select left digit. Press ▶ again to select another digit. Selected digit will flash. "1" indicates the menu item is disabled. "0" indicates the item is enabled.

Press ▲ to select "0" or "1" for flashing digit

- 2 Alarm Setup
- 3 Alarm setpoint value programming
- 4 Analog output scaling
- 5 Serial interface setup







Press the key until Loc 3 is displayed. Lockout 3 controls the operation of the front panel push-buttons when the meter is in the normal mode of operation.

Press ▶ to display status and select left digit. Press ▶ again to select another digit. Selected digit will flash. "1" indicates the menu item is disabled. "0" indicates the item is enabled.

Press ▲ to select "0" or "1" for flashing digit

- 2 View peak value
- 3 View alarm setpoints
- 4 Reset (peak and latched alarms)
- 5 Reset (meter reset)

10.

### **SETUP MENU**

### MENU KEY

### **DIGIT SELECT KEY** ▶

**VALUE SELECT KEY** 

INPUT SIGNAL SCALING METHOD

#### 0.021 0.021 Lo in Press the **key** to store the Set the input signal to zero or Low signal input value low signal input. a known low value (not available for tC & rtd) 20.094 20.094 Hi In Press the **k**ey to store the Set the input signal to a High Signal Input Value high signal input. known high value 0.000 **0**.0000 0.**0**000 Lo rd Select 0 through 9 for Set Low Displayed Reading 0.00**0**0 0.000**0** flashing digit. Decimal point Select digit. Digit will flash for Low Signal Input location is fixed by dEC.Pt. 0.0000 0.000 **0**.0000 Hi rd Select 0 through 0.0000 Set High Displayed Reading Select digit. Digit will flash flashing digit. Decimal point for High Signal Input location is fixed by dEC.Pt.

### DIGIT SELECT KEY

VALUE SELECT KEY▲

#### TEMPERATURE SIGNAL CONDITIONER

InPut Input signal type	tC Thermocouple  Note: Display = K  rtd Pt 100 Ohm RTD	J°F J°C K°F K°C t°F t°C E°F E°C S°F S°C r°F r°C n°F n°C Types J, K, T, E, N, S, R in °C or °F  4d °F 4d °C DIN 4-wire 4A °F 4A °C ANSI 4-wire 3d °F 3d °C DIN 3-wire
		3A°F 3A°C ANSI 3-wire 2d°F 2d°C DIN 2-wire 2A°F 2A°C ANSI 2-wire Short Compensation for 2-wire lead resistance
	DC SIGNAL CONDITIONER	
	dC U DC Volts	0.2U       2.0U       20.0U         200.0U       660.0U         0.2, 2, 20, 200, 660 V FS
	dC A DC Amperes	<b>2.0a 20.0a 200.0a 5.0A</b> 2 , 20, 200 mA, 5 A FS
	rAtio Strain Gauge	<b>0.2U 2.0U 20.0U</b> 0.2, 2, 20 V FS
	TRUE RMS SIGNAL CONDITIONER	
	AC U AC Volts	0.2U 2.0U 20.0U 200.0U 660.0U 0.2, 2, 20, 200, 660 V FS
	AC A AC Amperes	<b>2.0a 20.0a 200.0a 5.0A</b> 2 , 20, 200 mA, 5 A FS

### MENU KEY **→**

### DIGIT SELECT KEY

### VALUE SELECT KEY▲

### LOAD CELL SIGNAL CONDITIONER

InPut Input signal type (continued)	Strn Load cells	20.0 50.0 100.0 250.50, 100, 250, 500 mV FS
	dC u DC millivolts	20.0 50.0 100.0 250.0 500.0 20, 50, 100, 250, 500 mV FS
SEtuP Meter Setup	<u><b>0</b></u> 0000 Display selection	<ul> <li>4 1/2 digits (0.1 Degree)</li> <li>Remote display</li> <li>4 1/2 digits [meter counts by 10] (.01 Degree)</li> <li>3 1/2 digits (1 Degree)</li> </ul>
	0 <u>0</u> 000 Line frequency	0 60 Hz 1 50 Hz
	00 <u>0</u> 00 Display of leading zeros	<ul><li>D Blank leading zeros</li><li>Display leading zeros</li></ul>
	000 <u>0</u> 0 Method of scaling meter	<ul><li>Scale factor and offset</li><li>Coordinates of 2 points</li></ul>
	Rear connector inputs A & B  A & B Logic levels for 6 & 7  A B DP1 DP2  1 1 XXXXX XXXX XXX XX 0 1 XXXX XX XX XXX X	<ul> <li>A: Reset B: Meter Hold</li> <li>A: Function Reset B:Peak Display</li> <li>A: Meter Hold B: Peak Display</li> <li>A: Meter Hold B: Tare</li> <li>A: Peak Display B: Tare</li> <li>A: Peak Display B: Tare</li> <li>External Decimal Pts.1</li> <li>External Decimal Pts.2</li> </ul>

### DIGIT SELECT KEY

ConFG Meter Configuration	00000 Operates as a rate of change meter Extended version only	<ul> <li>Not rate of change</li> <li>Rate x 0.1</li> <li>Rate x 1</li> <li>Rate x 10</li> <li>Rate x 100</li> <li>Rate x 1000</li> <li>Rate x 1000</li> <li>Rate x 10000</li> </ul>
	O0000 Selection of scaling by reading input signal or by Setup selection	Use setup scaling method Scale by reading input
	Selects between continuous (unlatched) data or single value (latched) of RS232 data when RTS is high or open	<ul><li>Unlatched</li><li>Latched</li></ul>
	00000 RS485 interface operates in the full duplex or half duplex mode	<ul><li>Full duplex mode</li><li>Half duplex mode</li></ul>
	00000 Scaling for nonlinear input Extended version only	<ul><li>Linear input</li><li>Custom curve</li></ul>
<b>FiLtr</b> Filtering	<b>0</b> 0000 Alarm filtering	Output is unfiltered Output is filtered
	00000 Peak display filtering	Peak of unfiltered signal Peak of filtered signal
	00 <u>0</u> 00 Display filtering	<ul><li>Datch average, 16 rdgs</li><li>Display filtered signal</li></ul>

### DIGIT SELECT KEY

FiLtr Filtering (continued)	Adaptive filter response  00000 Input signal filtering	<ul> <li>Low threshold level</li> <li>High threshold level</li> <li>Autofilter</li> <li>Batch avg, 16 rdgs.</li> <li>Moving avg, .08 sec.</li> <li>Moving avg, .15 sec.</li> <li>Moving avg, .3 sec.</li> <li>Moving avg, .6 sec.</li> <li>Moving avg, 1.2 sec.</li> <li>Moving avg, 2.4 sec.</li> <li>Moving avg, 4.8 sec.</li> <li>Moving avg, 9.6 sec.</li> <li>Unfiltered</li> </ul>
dEc.Pt Decimal point selection	d <u>.</u> dddd	d.dddddd.dddddd.dddddddddddd.ddddd
(Scale and Offset selected) SCALE Scale factor multiplier (not available for tC)	0.0000       0.0000         0.0000       0.0000         0.0000       0.0000	Select 0 through 9 for flashing digit and decimal point location when decimal point is flashing
OFFSt Offset or Zero Value	0.0000       0.0000       0.0000         0.0000       0.0000       0.0000	Select 0 through 9 for flashing digit. Decimal point location is fixed by dEC.Pt selection
(coordinates of 2 pts method)  Lo in  Low signal input value (not available for tC & rtd)	0.0000       0.0000       0.0000         0.0000       0.0000	Select 0 through 9 for flashing digit. Decimal point location is fixed by input range chosen.
Lo rd Low Displayed Reading at Low Signal Input	0.0000       0.0000       0.0000         0.0000       0.0000	Select 0 through 9 for flashing digit. Decimal point location is fixed by dEC.Pt selection
<b>Hi In</b> High Signal Input Value	0.0000 0.0000 0.0000 0.00 <u>0</u>	Select 0 through 9 for flashing digit. Decimal point location determined by input range chosen.

### DIGIT SELECT KEY

Hi rd High Displayed Reading at High Signal Input	0.0000       0.0000       0.0000         0.0000       0.0000	Select 0 through 9 for flashing digit. Decimal location is fixed by dEC.Pt selection.
ALSEt Alarm Operation Setup (Only enabled if relay output is installed).	00000 Relay state when alarm is active	<ul> <li>Relay 1 on, Relay 2 on</li> <li>Relay 1 off Relay 2 on</li> <li>Relay 1 on, Relay 2 off</li> <li>Relay 1 off, Relay 2 off</li> <li>Relay 2 off</li> </ul>
	00000 Alarm latching or nonlatching	<ul> <li>Alarm 1 nonlatching,     Alarm 2 nonlatching</li> <li>Alarm 1 latching,     Alarm 2 nonlatching</li> <li>Alarm 1 nonlatching,     Alarm 2 latching</li> <li>Alarm 1 latching,     Alarm 2 latching,     Alarm 2 latching</li> </ul>
	Alarm status	<ul> <li>Q AL1 active high     AL2 active high</li> <li>1 AL1 active low     AL2 active high</li> <li>2 AL1 disabled     AL2 active high</li> <li>3 AL1 active high     AL2 active low     AL2 active low     AL1 active low     AL2 active low</li> <li>6 AL1 disabled     AL2 active high     AL2 active low</li> <li>6 AL1 active high     AL2 disabled</li> <li>7 AL1 active low     AL2 disabled</li> <li>8 AL1 disabled     AL2 disabled</li> </ul>

DIGIT SELECT KEY ▶

ALSEt (continued) Alarm Operation Setup	O0000 Selection of Hysteresis mode or Band Deviation mode of alarms.	<ul> <li>AL1 Band deviation</li></ul>
	Number of readings in the alarm zone to cause an alarm	<ul> <li>After 1 reading</li> <li>After 2 readings</li> <li>After 4 readings</li> <li>After 8 readings</li> <li>After 16 readings</li> <li>After 32 readings</li> <li>After 64 readings</li> <li>After 128 readings</li> </ul>
dEU1H  Amount of deviation or hysteresis - Alarm 1 (Only enabled if relay output is installed).	When the deviation value is	Select 0 through 9 for flashing digit.
dEU2b  Amount of deviation or hysteresis - Alarm 2 (Only enabled if relay output is installed).	00000 00000 00000  When the deviation value is >0, the alarms operate above and below setpoint by the value entered.	Select 0 through 9 for flashing digit.
An Set  Setup of analog output.  (Only enabled if analog output	Q0 Calibrated output is current or voltage.	<ul><li>Current output</li><li>Voltage output</li></ul>
board is installed).	00 Analog output filtering	<ul><li><u>0</u> Analog output unfiltered</li><li><u>1</u> Analog output filtered</li></ul>

### MENU KEY 🛏

### DIGIT SELECT KEY

(if analog output installed)  An Lo  Displayed value for 0 voltage or current output	0.0000 0.0 <u>0</u> 000 0.000 <u>0</u> 0.000 <u>0</u>	Select 0 through 9 for flashing digit. Decimal point location fixed by dEC.Pt selection.
An Hi Displayed value for 10 volts or 20 mA output	<u><b>0</b></u> .0000	Select 0 through 9 for flashing digit. Decimal fixed by DEC.Pt selection.
(if serial interface is installed)  Ser_1  Serial interface setup	<u>0</u> 00 Output filtering	<ul><li>Send unfiltered signal</li><li>Send filtered signal</li></ul>
Fixed Parameters No parity 8-bit word 1 stop bit	0 <u>0</u> 0 Baud rate	<ul> <li>300 baud</li> <li>600 baud</li> <li>1200 baud</li> <li>2400 baud</li> <li>4800 baud</li> <li>9600 baud</li> <li>19200 baud</li> </ul>
	Digital output rate (in seconds)	60 Hz 50 Hz Line frequency 1 .28 sec .34 sec 2 .57 sec .68 sec 3 1.1 sec 1.4 sec 4 2.3 sec 2.7 sec 5 4.5 sec 5.4 sec 6 9.1 sec 10.9 sec 7 18.1 sec 21.8 sec 8 36.3 sec 43.5 sec 9 72.5 sec 87 sec
Ser 2 Serial interface setup	<u>0</u> 000 Line Feed	<ul><li>None after carriage rtn</li><li>LF after carriage return</li></ul>
	O000 Alarm data transmitted with meter readings	No alarm data     Alarm data with reading
	00 <u>0</u> 0 Control of digital output	Output on RS-232 / RS-485 command only

MENU KEY ➡

DIGIT SELECT KEY

Ser 2 (continued) Serial interface setup	Meter address for RS-232/RS-485 communication ( digit display, address number of meter)  Note: Addresses 1 through 15 are denoted by 1 through 9 and A through F. Addresses 16 through 31 use the same character followed by a decimal point.	Meter#  1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31	Display 1 2 3 4 5 6 7 8 9 a b C d E F 0.1. 2.3. 4. 5. 6. 7. 8. 9. A b C d E F.
Loc 1  Lockout of Menu Items (Lockout jumper must be removed to access Loc 1, 2, 3. See Figure 9.1)	00000 Input type selection  00000 Meter setup, configuration	<ul><li>© Enabled</li><li>1 Disabled</li><li>© Enabled</li><li>1 Disabled</li></ul>	
	and decimal point selection.  00000  Filter	<ul><li><u>0</u> Enabled</li><li><u>1</u> Disabled</li></ul>	

MENU KEY **→** 

### DIGIT SELECT KEY

Loc 1 (continued) Lockout of Menu Items (Lockout jumper must be removed to access Loc 1, 2, 3.	000 <u>0</u> 0 Scale or Lo, Hi Input	<ul><li>① Enabled</li><li>① Disabled</li><li>① Enabled</li></ul>
See Figure 9.1)	Offset or Lo, Hi Reading	1 Disabled
Loc 2 Lockout of Front Panel Keys (Lockout jumper must be re-	<u><b>0</b></u> 0000 Alarm Setup	<ul><li><u>0</u> Enabled</li><li><u>1</u> Disabled</li></ul>
moved to access Loc 1, 2, 3. See Figure 9.1)	O <u>0</u> 00  Alarm setpoint programming	<ul><li><u>0</u> Enabled</li><li><u>1</u> Disabled</li></ul>
	00 <u>0</u> 0 Analog output scaling	<ul><li>① Enabled</li><li>1 Disabled</li></ul>
	000 <u>0</u> Serial interface setup	<ul><li>0 Enabled</li><li>1 Disabled</li></ul>
Loc 3  Lockout of Front Panel Keys (Lockout jumper must be re-	<b>0</b> 000 View peak value pushbutton	<ul><li>0 Enabled</li><li>1 Disabled</li></ul>
moved to access Loc 1, 2, 3. See Figure 9.1)	0000 View alarm setpoints push- button	<ul><li>0 Enabled</li><li>1 Disabled</li></ul>
	00 <u>0</u> 0  Reset pushbutton (peak and latched alarms)	<ul><li>0 Enabled</li><li>1 Disabled</li></ul>
	Reset pushbutton (meter reset)	<ul><li>Enabled</li><li>Disabled</li></ul>

### 11. DC VOLTS & AMPS

This section is designed to provide basic meter setup instructions when a direct readout of voltage or current is required. When an external shunt is used to monitor current, the setup for process signals, section 12, should be used. Some menu items, such as leading zero blanking, display filtering, etc., are not discussed in this section and have been set to the most commonly used values. Should these items require change, refer to section 10 for selection information. For configuration of optional boards, see the appropriate section elsewhere in the manual.

#### 11.1 RANGE JUMPER SELECTIONS




Figure 11.1 DC Signal Conditioner

- **Notes** 1. See Section 22 to select 5,10 or 24Vdc excitation.
  - 2. Jumpers designated by capital letters require 5mm (0.2in) jumpers. Jumpers designated by lower case letters require 2.5mm (0.1 in) jumpers.
  - 3. Spare jumpers should be stored on single unused jumper posts not associated with capital letter designations

#### 11.2 MENUSELECTION

Whenever the scale factor is 1.0 and offset is zero, the meter displays a direct readout of the signal input in (milli)volts or (milli)amperes. In the following example, the meter is configured for a full scale display of 0 to 20V or 0 to 20mA equals 0 to 20.000. Other ranges follow the same setup format. Note that the decimal point selection does not affect the displayed value. A full scale value of 20000 may be displayed as 20.000 milliamps or 20000 microamps. During setup, it may be necessary to enable some menu items that are locked out. See Section 9 for further information.

MENU KEY ►

### DIGIT SELECT KEY

**VALUE SELECT KEY** 

# InPuE

Press the key to display InPut (Input type selection).

Note: Selection of input type & range must match jumper selection in Section 11.1

# dC U

Press until dC U
(dc Volts) is displayed

or dC A (DC Amps) is displayed.

# 20.00

Press ▲ to select 0.2V, 2.0V, 20.0V, 200.0V, 660.0V



or 2.0a, 20.0a, 200.0a (milliamps) or 5.0A (Amps)

# SELUP

Press the key to display SEtuP. (Basic setup) See Section 9, Page 10 for detailed description of selections for digits 1 through 5.



Press ▶ to display status and select left digit. Press ▶ again to select another digit. Selected digit will flash.



Press **\( \Lambda \)** to select value for flashing digit.

Digit 1:

"0"= 20,000 cts. full scale
"3"=2,000 cts. full scale
Digit 4:

"0" = scale and offset method

# dEc.PE

Press the key to display dEcPt (Decimal point)



Press ▶ to display location of decimal point.



Press **\Lambda** to change decimal point location.

# SCALE

Press the key to display SCALE (Scale factor).

# 005.00

Press to display value and select left digit. Press again to select another digit.



Use ▲ to set digit values. Set value and decimal to 1.0 (1.0000, 01.000, etc)

# OFF5E

Press the key to display OFFSt (Zero offset).

# 0 1250

Press to display value and select left digit. Press again to select another digit.

# 00.000

Use ▲ to set digit values. Set value to 00.000. Decimal point is fixed by Dec.Pt.

### rESEŁ




Press the key. Continue to press (or and simultaneously) until rESEt is displayed. The meter will now go to the operating mode and display the value of the input signal.

### **PROCESS SIGNAL INPUTS**

This section provides basic meter setup instructions for a direct readout in engineering units such as psi, rpm, etc. The signal input may come from a transducer or other voltage or current source. Some menu items, such as leading zero blanking, display filtering, etc., are not discussed in this section and have been set to the most commonly used values. Should these items require change, refer to section 10 for selection information. For configuration of optional boards, see the appropriate section elsewhere in the manual.

#### 12.1 RANGE JUMPER SELECTIONS

	Voltage
Input	Jumpers Required
200mV	E, b
2V	E, a
20V	F, g, b
200V	F, g, a
660V	F, h, a
	•



Input Jumpers Required

2mA D, h, b

20mA C, h, b

200mA B, h, b

5A A, h, b

Figure 12.1 DC Signal Conditioner

#### Notes

- 1. See Section 22 to select 5, 10 or 24Vdc excitation.
- 2. Jumpers designated by capital letters require 5mm (0.2in) jumpers. Jumpers designated by lower case letters require 2.5mm (0.1 in) jumpers.
- 3. Spare jumpers should be stored on single unused jumper posts <u>not</u> associated with capital letter designations

#### 12.2 MENUSELECTION

Display in engineering units is most easily programmed using the coordinates of 2 points. There are two methods. The first is to enter the 4 values (low signal input, desired reading at the low signal input, high signal input, and desired reading at the high signal input) directly via the front panel pushbuttons or the RS232 interface. The second method is to have the meter read the signal input at a known low value and store that reading as the low in and read a known high signal value and store that value as high in. The low and high known values are entered as the lo rd and hi rd. An example of using the reading the input method of coordinates of 2 points is shown for the load cell meter, Section 17. Selecting the reading method (menu item "config" digit 2 set to 1) overides either method of scaling selected in "setup". The following example is the 2 coordinate method of directly entering the 4 values.

To set up the range using coordinates of 2 points, values for low signal input, low display, high signal input and high display are entered. The following example uses this scaling method. Signal input is 4 to 20mA and displayed value is 000.00 (at 4mA) to 100.00 (at 20mA). When setting up the meter, it may be necessary to enable some menu items. See Section 9 for further information.

### MENU KEY **➡**

### DIGIT SELECT KEY

### **VALUE SELECT KEY▲**

### InPub

Press the key to display InPut (Input type selection).

Note: Selection of input type & range must match jumper selection in Section 12.1.

# dC A

Press until dC A (DC Amperes) is displayed. (dC U if voltage input).

# 20.03

Press ▲ to select 2.0a, 20.0a, 200.0a (milliamps) or 5.0A (Amps). (.20U, 2.0U, 20.0U, 200.0U or 660.0U if voltage input)

# SELuP

Press the key to display SEtuP. (Basic setup)
See Section 9, Page 10 for detailed description of selections for digits 1 through 5.

# 30000

Press ▶ to display status and select left digit. Press ▶ again to select another digit. Selected digit will flash.

# 1 2 3 4 5

Press **\( \Lambda \)** to select value for flashing digit.

Digit 1: "0"= 20,000 cts "3"=2.000 cts

Digit 4: "0"=scale & offset "1"=2- coordinate

# dEc.PE

Press the key to display dEcPt (Decimal point).

# *d.dddd*

Press to display decimal point location

Press **\Lambda** to change decimal point location.

# Lo in

Press the key to display Lo in (Low signal input value).

# 00.000

Press to display value and select left digit. Press again to select another digit.. Dec pt. fixed by input range

# 04.000

Use ▲ to set digit values and set to 04.000 (4 mA). Most significant digit may be set to 0 thru 9 and -0 thru -9.

### Lo rd

Press the key to display Lo rd (Desired meter reading at low signal input).

Press ▶ to display value and select left digit. Press ▶ again to select another digit. Decimal point set by Dec.Pt.

# 000.00

Use **\( \Lambda \)** to set digit values and set to 000.00.

# Hı In

Press the key to display Hi in (High signal input value).

# 00.000

Press to display value and select left digit. Press again to select another digit. Dec pt. fixed by input range

# 20.000

Use ▲ to set digit values and set to 20.000 (20 mA).

DIGIT SELECT KEY

**VALUE SELECT KEY** 







Press the key to display Hi rd (Desired meter reading at high signal input).

Press ► to display value and select left digit. Press ► again to select another digit. Decimal point set by Dec.Pt.

Use **\( \Lambda \)** to set digit values and set to 000.00.

rESEŁ



Press the key. Continue to press (or and simultaneously) until rESEt is displayed. The meter will now go to the operating mode and display the value of the input signal.

13.

### **THERMOCOUPLES**

#### 13.1 RANGE JUMPER SELECTIONS

### **Thermocouple Type**

Туре	Jumpers Required
J, K, E, N	f
T, R, S	e

### **Open Thermocouple**

Open TC Indication	Jumpers Required
Upscale	c
Downscale	d




Figure 13.1 Temperature Signal Conditioner

#### 13.2 MENUSELECTION

Thermocouple type and Celsius or Fahrenheit scale are selected by input type. However, Kelvin or Rankine may be displayed by entering the appropriate offset to the selected scale. Although 0.01 degree resolution may be selected, it is not recommended for use with thermocouples. When setting up the meter, it may be necessary to enable some of the menu items. See Section 9 for further information.

DIGIT SELECT KEY

**VALUE SELECT KEY** 

# InPuE

Press the key to display InPut (Input type selection).

Note: Selection of input type & range must match jumper selection in Section 13.1.

# ŁΓ

Press ▶ to display input selected. Press ▶ again until tC (thermocouple) is displayed.

# J of

Press ▲ to select thermocouple type J, K, T, E, R, S and °C or °F scale (J°F, J°C, K°F, K°C, t°F, t°C, E°F, E°C, r°F, r°C, S°F, S°C)

# SELuP

Press the key to display SEtuP. (Basic setup)
See Section 9, Page 10 for detailed description of selections for digits 1 through 5.



Press ▶ to display status and select left digit. Press ▶ again to select another digit. Selected digit will flash.



Press **\( \Lambda \)** to select value for flashing digit.

Digit 1:

"0"= 0.1 degree resolution
"3"=1 degree resolution

# OFF5Ł

Press the key to display OFFSt (Zero offset).



Press ► to display value and select left digit. Press ► again to select another digit.



Use ▲ to set digit values and set to 000.00 for °F and °C or



set value to 273.2 if °C is selected to display in °Kelvin and 459.7 if °F is selected to display in ° Rankine.

### rESEL

45 1.9

Press the key. Continue to press (or and simultaneously) until rESEt is displayed. The meter will now go to the operating mode and display the value of the input signal.

14.1 RANGE JUMPER SELECTION

All RTD Types

Jumpers Required
2-,4-wire

b, f

Jumpers Required
3--wire

a, f

Note: See Section 22 to select 10 Vdc excitation.

Figure 14.1 Temperature Signal Conditioner

#### 14.2 2-WIRE RTD LEAD COMPENSATION

This section describes how to remove the error caused by lead resistance in a 2-wire RTD. Ambient temperature changes will cause some error in the readings; the higher the lead resistance, the greater the error. When performing this procedure, the leads should be shorted together as close as possible to the RTD. This step is not necessary when using 3- or 4-wire RTD's since lead resistance compensation is automatic in the meter. When setting up the meter, it may be necessary to enable some of the menu items. See Section 9 for further information.

#### 14.3 MENUSELECTIONS

The following example is setup for a 4-wire DIN RTD. When setting up the meter, it may be necessary to enable some of the menu items. See Section 9 for further information.

MENU KEY

DIGIT SELECT KEY

**VALUE SELECT KEY▲** 

InPuE

Press the key to display InPut (Input type selection).

Note: Selection of input type & range must match jumper selection in Section 14.1.

rEd

Press until rtd (resistance temperature detector) is displayed

40 0[

Press ▲ to select rtd type (4d°F, 4d°C, 4A°F, 4A°C, 3d°F, 3d°C, 3A°F, 3A°C, 2d°F, 2d°C, 2A°F, 2A°C)

Number = # of leads

Letter = Din or ANSI RTD

SELuP

Press the key to display SEtuP. (Basic setup)
See Section 9, Page 10 for detailed description of selections for digits 1 through 5.

30000

Press ► to display status and select left digit. Press ► again to select another digit. Selected digit will flash.

00000

Press to select value for flashing digit.

Digit 1:

"0"= 0.1 degree resolution
"2" = 0.01 degree resolution
"3"=1 degree resolution

<u> SERLE</u>

Press the key to display SCALE. Divide 100 by resistance of RTD at 0° C to calculate scale factor.

005.00

Press to display value and select left digit. Press again to select another digit.

.99706

Use **\( \Lambda \)** to set digit values. Set value and decimal to calculated scale factor.

OFF5Ł

Press the key to display OFFSt (Zero offset).

0000.0

Press ► to display value and select left digit. Press ► again to select another digit.

0000.0

Use ▲ to set digit values and set to 0.0 for °F and °C or

0273.2

set value to 273.2 if °C is selected to display in °Kelvin and 459.7 if °F is selected to display in ° Rankine.

rESEL

85.00

Press the key. Continue to press (or and simultaneously) until rESEt is displayed. The meter will go to the operating mode and display the value of the input signal.

### STRAIN GAUGES AND POTENTIOMETERS

#### 15. 1 RANGE JUMPER SELECTIONS

	Voltage
Input	Jumpers Required
200mV	E, b
2V	E, a
20V	F, g, b

#### **Notes**

- 1. See Section 22 to select 10V removejumpers for externation.
- Jumpers designated by lowe letters require 2.5mm (0.1 in) j
- Spare jumpers should be sto single unused jumper posts.




Figure 15. 1 DC Signal Conditioner

#### 15. 2 MENUSELECTION

Display in engineering units is most easily programmed using the coordinates of 2 points. There are two methods. The first is to enter the 4 values (low signal input, desired reading at the low signal input, high signal input, and desired reading at the high signal input) directly via the front panel pushbuttons or the RS232 interface. The second method is to have the meter read the signal input at a known low value and store that reading as the low in and read a known high signal value and store that value as high in. The low and high known values are entered as the lo rd and hi rd. An example of using the reading the input method of coordinates of 2 points is shown for the load cell meter, Section 17. Selecting the reading method (menu item "config" digit 2 set to 1) overides either method of scaling selected in "setup". To set up the range using coordinates of 2 points, values for low signal input, low display, high signal input and high display are entered. The following example uses this scaling method. Signal input is 0 to 20mV and displayed value is 000.00 (at 0mV) to 100.00 (at 20mV). When setting up the meter, it may be necessary to enable some menu items. See Section 9 for further information.

MENU KEY

DIGIT SELECT KEY

VALUE SELECT KEY▲



Press the key to display InPut. **Note:** Range selection must match jumper selection in Section 15. 1.

rAL io

Press until rAtio (Ratiometric operation) is displayed.

0.20

Press ▲ to select 0.2U, 2.0U or 20.0U (200mV, 2V or 20Vdc).

DIGIT SELECT KEY

**VALUE SELECT KEY** 

# 5ELuP

Press the key to display SEtuP. (Basic setup). See Section 9, Page 10 for detailed description of selections for digits 1 through 5.

# 30000

Press ► to display status.

Press ► again to select another digit. Selected digit will flash.



Press ▲ to select value.

Digit 1:"0"= 20,000 cts. FS

"2"=LSD fixed zero

"3"=2,000 cts. FS

Digit 4: "1" for 2 point scaling

# dEc.PE

Press the key to display dEcPt (Decimal point).



Press to display decimal point location.



Press **\( \)** to select decimal point location.



Press the key to display Lo in (Low signal input value).

# .00000

Press to display value.

Press again to select another digit. **Note:** Decimal point is fixed by input range selection.



Use ▲ to set digit values and set to .00000 (0mV).

Note: Most significant digit may be set to 0 thru 9 and -0 thru -9.

### Lo rd

Press the key to display Lo rd (Desired meter reading at low signal input).



Press to display value.

Note: Decimal point is fixed by dEcPt selection.



Use ▲ to set digit values and set to 000.00

# Hı In

Press the key to display Hi in (High signal input value).

# .00000

Press to display value.

Note: Decimal point is fixed by input range selection.

# .02000

Use ▲ to set digit values and set to .02000 ( 20mV )

# Hı rd

Press the key to display Hi rd (Desired meter reading at high signal input).

# 000.00

Press to display value.

Note: Decimal point is fixed by dEcPt selection.

# 100.00

Use ▲ to set digit values and set to 100.00

# rE5EŁ

Press the key. Continue to press (or and simultaneously) until rESEt is displayed. The meter will now go to the operating mode and display the value of the input signal.

### AC (RMS) VOLTS & AMPS

This section provides basic setup instructions for true RMS voltage or current monitoring. An RMS signal conditioner is required. Some menu items, such as leading zero blanking, display filtering, etc., are not discussed in this section and have been set to the most commonly used values. Should these items require change, refer to section 10 for selection information. For configuration of optional boards, see the appropriate section elsewhere in the manual.

#### 16. 1 RANGE JUMPER SELECTIONS Voltage Jumpers Required Input AC Coupled 200mV E, k 2V E, i 20V F, g, k 200V F, g, j 660V F, h, j Current Jumpers Required AC Coupled Input 2mA D. h. k 20mA C, h, k 200mA B, h, k 5A A, h, m

Figure 16. 1 RMS Signal Conditioner

#### Notes

- 1. Jumpers designated by capital letters require 5mm (0.2in) jumpers. Jumpers designated by lower case letters require 2.5mm (0.1 in) jumpers.
- 2. Spare jumpers should be stored on single unused jumper posts <u>not</u> associated with capital letter designations

#### 16. 2 MENUSELECTION

Whenever the scale factor is 1.0 and offset is zero, the meter displays a direct readout of the signal input in (milli)volts or (milli)amperes. In the following example, the meter is configured for a full scale display of 0 to 20V or 0 to 20mA equals 20.000. Other ranges follow the same setup format. Note that the decimal point selection does not affect the displayed value. A full scale value of 20000 may be displayed as 20.000 Volts or 20000 millivolts. When an external shunt or current transformer is used to monitor current, the appropriate scale factor must be entered. A 5A CT input to the meter displays 20000 (2000 when 3 1/2 digit is selected). For an 800 Amp CT, divide 8000 (desired full scale display with .1 Amp resolution) by 20000 (full scale when the scale factor is 1.0) for the correct scale factor. Enter .4 as a scale factor. During setup, it may be necessary to enable some menu items that are locked out. See Section 9 for further information.

MENU KEY **➡** 

#### DIGIT SELECT KEY

**VALUE SELECT KEY** 

# InPuE

Press the key to display InPut (Input type selection).

**Note:** Selection of input type & range must match jumper selection in Section 16. 1.

# AC U

Press until AC U (ac Volts) is displayed or



AC A (ac Amperes) is displayed.

# 20.0U

Press ▲ to select 0.2V, 2.0V, 20.0V, 200.0V or 660.0V or



2.0a, 20.0a, 200.0a (milliamps) or 5.0A (Amps)

# SELuP

Press the key to display SEtuP. (Basic setup). See Section 9, Page 10 for detailed description of selections for digits 1 through 5.

# 30000

Press to display status and select left digit. Press again to select another digit. Selected digit will flash.

# 1 2 3 4 5

Press **\( \Lambda \)** to select value for flashing digit.

Digit 1:

"0"= 20,000 cts. full scale
"2"=Same as "0" but LSD is
fixed zero.

"3"=2,000 cts. full scale Digit 4:

Set to "0" for scale and offset

# dEc.Pb

Press the key to display dEcPt (Decimal point).

# dddd

Press to display decimal point location.

# ddddd

Press **\( \Lambda \)** to select decimal point location.

# <u>SEALE</u>

Press the key to display SCALE (Scale factor).

# 005.00

Press to display value and select left digit. Press again to select another digit.

Use **\( \Lambda \)** to set digit values. Set value and decimal to 1.0 or appropriate multiplier for external shunts or CT's.

# OFF5E

Press the key to display OFFSt (Zero offset).

# 0 1250

Press to display value and select left digit. Press again to select another digit.

# 00.000

Use ▲ to set digit values. Set value to 00.000. Decimal point is fixed by Dec.Pt.

### rE5EE

20000

Press the key. Continue to press (or and simultaneously) until rESEt is displayed. The meter will now go to the operating mode and display the value of the input


#### **17**.

### **LOADCELLS AND MICROVOLT INPUTS**

This section provides setup instructions for use as a microvoltmeter or with load cells and strain gauges. 10 Volt excitation will power up to 4 350 Ohm load cells. Sense leads may be used to compensate for lead resistance of the excitation supply. For configuration of optional boards, see the appropriate section elsewhere in the manual.

#### 17.1 RANGE JUMPER LOCATIONS

Input	Jumper	Full Scale Display
	Locations	Scale factor = 1
20mV	е	20000
50mV	а	50000
100mV	b	10000
250mV	С	25000
500mV	d	50000



Notes

- 1. See Section 22 to select 10V excitation.
- 2. Jumpers are 2.5mm (0.1 in).

### Figure 17.1 Load Cell Signal Conditioner

#### 17.2 MENUSELECTION

To scale the meter using the reading method of coordinates of 2 points, the low signal input and high signal input are read directly by the meter and are stored as Lo in and Hi in. For example, the full scale range of a load cell is 500 pounds and has an output of 2mV/V. With 10V excitation, the full scale range of 20mV selected. The resolution is .01 pounds. With no weight on the scale, the meter should read 0.00 and with a 500 pound weight on the scale the meter should display 500.00 pounds. With no weight on the scale, press the menu key to select Lo inand press the digit select key. The meter will take readings and display the millivolt value of the input signal. Pressing the value select key will store this reading as Lo in. Press the menu key to select Hi in, place the 500 pound weight on the scale and repeat the procedure the same as for Lo in. Press the menu key to select lo rd (Low reading) and enter 000.00, then press the menu key to select Hi rd (High reading) and enter 500.00. Advantages of this method are accuracy, since reading the value corrects for any error in the transducer, and ease of recalibration. To recalibrate the meter, take readings at 0 and 500 pounds, Lo rd and Hi rd do not need to be reentered. If a 500 lb. weight was not available, the same result can be achieved by using any known weight. During setup, it may be necessary to enable some menu items. See Section 9 for further information. See Section 12, Process Meters, for an example scaling by direct entry of the input values.



MENU KEY ➡

DIGIT SELECT KEY

**VALUE SELECT KEY** 

# ConfG

Press the key to display ConFG(configuration). See Section 9, Pg 13 for detailed description of digits 1 thru 5.

00000

Press ► to display status.

Press ► again to select digit. Selected digit will flash.

1 2 3 4 5

Press ▲ to select value.

Digit 2:"1"= Reading input 2 coodinate method of scaling.

dEc.PE

 d.d d d d

Press to display decimal point location.

ddddd

Press **A** to change decimal point location.

rESEL

Press the key. Continue to press (or and simultaneously) until rESEt is displayed. The meter will go to the operating mode and display the value of the input

sign In

Press the key to display Lo in (Low signal input value). Apply an input for a known low value.

000.29

Press to display input signal. Meter will momentarily blank and then display a reading.

00029

Use **\( \Lambda \)** to store reading as low input

H<sub>1</sub> In

Press the key to display Hi in (High signal input value). Apply an input for a known high value.

19.957

Press to display input signal. Meter will momentarily blank and then display a reading.

19.957

Use ▲ t o set digit values and set to 20.000mV.

Lo rd

Press the key to display Lord (Desired meter reading at low signal input).

00000

Press ▶ to display value and select left digit. Press ▶ again to select another digit. Decimal point set by dEc.Pt

00000

Use **to set digit values** and set to 0.

Hı rd

Press the key to display Hi rd (Desired meter reading at high signal input).

500.00

Press to display value and select left digit. Press again to select another digit. Decimal point set by dEc.Pt.

| *500.00* 

Use ▲ to set digit values and set to 500.00.

rE5EL

500.00

Press the  $\Longrightarrow$  key. Continue to press  $\Longrightarrow$  (or  $\Longrightarrow$  and  $\blacktriangle$  simultaneously) until rESEt is displayed. The meter will go to the operating mode and display the value of the input signal.

18.

#### **DUAL ALARM OUTPUTS**

#### 18.1 OPERATING MODE MENU SELECTION

When setting up the meter, it may be necessary to enable some of the menu items. See Section 9 for further information.

### MENU KEY ►

### DIGIT SELECT KEY

### **VALUE SELECT KEY**

# ALSEL

Press the key until ALSEt (Alarm setup) is displayed. See Section 9, ALSEt for detailed selection information for Digits 1 through 5.

# 00000

Press ► to display status.

Press ► again to select digit. Selected digit will flash.



Press **\( \Lambda \)** to select value for flashing digit

**Digit 1**:Relay state in alarm **Digit 2**: Latching or non-latch-

ing output

**Digit 3:** Alarm high, low, or disabled

Digit 4: Hysteresis or deviation

**Digit 5:** Time delay

# dEU 15

Press the key and dEU1b (Alarm 1 band deviation) or dEU1H (Alarm 1 hysteresis) is displayed if ALSEt digit 4 is not set to 4.



Press to display value.

Press again to select digit. Selected digit will flash.



Using ▲ to select digit and ► to set digit value, enter deviation value for setpoint 1 Relays turn on and off at setpoint if value is zero.



Press the key and dEU2b (Alarm 2 band deviation) or dEU2H (Alarm 2 hysteresis) is displayed if ALSEt digit 4 is not set to 4.



Press to display value.

Press again to select digit. Selected digit will flash.



Using ▲ to select digit and ▶ to set digit value, enter deviation value for setpoint 2 Relays turn on and off at setpoint if value is zero.

#### 18.2 NORMAL OPERATION

When deviation and hysteresis are not enabled or deviation is set to zero, the alarm energizes at and above the setpoint and deenergizes below the setpoint if high alarm is selected. The alarm energizes at and below the setpoint and deenergizes above the setpoint if low alarm is selected. The setpoint value is not displayed if the alarm is disabled.

#### 18.3 BAND DEVIATION

When deviation is selected from the setup menu, a value is entered for the amount of deviation required. This value represents the number of counts at which the relay will be energized above and below the setpoint. For example, if the setpoint is set to 10,000 and a deviation value of 200 was entered, the relay will activate below 9800 and above 10,200.

#### 18.4 HYSTERESIS

When hysteresis is selected from the setup menu, a value is entered for the amount of hysteresis required. This value represents the number of counts at which the relay will be energized above and deenergized below the setpoint. For example, if the setpoint is set to 10,000 and a hysteresis value of 200 was entered, the relay will activate at 10200 and deactivate at 9800.

#### 18. 3 VIEWING AND CHANGING SETPOINTS

When viewing or changing the setpoint values, it is not necessary to enter the setup menu. This allows the meter to continue conversions and provide outputs when the setpoints are displayed.



DIGIT SELECT KEY

VALUE SELECT KEY▲



Press the ALARMS key to display Alarm 1 value.



Alarm value blinks and Alarm 1 LED indicator lights. Press to select digit.



Using ▶ to select digit and ▲ to set digit value, enter setpoint 1 value.



Press ALARMS key again to display Alarm 2 value



Alarm value blinks and Alarm 2 LED indicator lights. Press to select digit.



Using ► to select digit and to set digit value, enter setpoint 2 value.



Press key again. The meter resets and then displays the present reading.

#### 19.

### **ANALOG OUTPUT**

The analog output option provides a 0 to 20mA and a 0 to 10Vdc linear signal derived from the displayed reading. The low signal output and high signal output may be set to equal any displayed value. Although both outputs are available, only one is calibrated to specifications. The other output is accurate to +/-1% of the displayed value typical (2%max).


#### 19. 1 4 TO 20MA OUTPUT SCALING

The output is scaled by selecting a displayed value for the low signal output and a displayed value for the high signal output. For a current output, the low value is 0mA and the high output is 20mA. To scale a signal for 4 to 20 mA, the following procedure must be used:

- 1. Desired display value for 20mA Desired display value for 4mA = Display span
- 2. Display span / 4 = Offset value
- 3. Desired display value for 4mA Offset value = **An Lo**
- 4. **An Hi** = Desired display value for 20mA

#### 19. 2 ANALOG OUTPUT SETUP SOFTWARE

The following menu items are accessible only with an Analog Output option installed and appropriate lockouts enabled. See Section 10 for further information. Setup Example: 4mA to 20mA out = 5000 counts to 15000 counts (See Section 19.1).



### RS-232 AND RS-485 INTERFACE

#### 20. 1 OPERATING MODE MENU SELECTION

The following menu items are accessible only with an RS-232 or RS-485 option installed and appropriate lockouts enabled. See Section 10 for further information.



### DIGIT SELECT KEY

### VALUE SELECT KEY▲

Press the key until SEr 1 (Serial interface setup 1) is displayed.



1 2

Press **t** to display status. again to select Press digit. Selected digit will flash.

Digit 3: Output filtering

Digit 4: Baud rate

Digit 5: Output update rate



2 Press to select value

for flashing digit 3: "0"- Send unfiltered signal

"1"- Send filtered signal 4: "0" - "6" -300 to 19.2K baud

5: "0"- "9"-60/sec to 1/15min



Press the key until SEr 2 (Serial interface setup 2) is displayed.



Press to display status. Press again to select digit.

Digit 2: Line feed

Digit 3: Alarm data sent with meter readings

**Digit 4:** Control of output

**Digit 5:** Meter address



Press A to select value for flashing digit

2: "0"-no line feed "1"-<LF> after <CR>

3: "0"-no alarm data "1"-alarm data sent

4: "0"-continuous output "1"-output on command

5: "1" to "F" & "0." to "F." -Meter #1 to Meter #31

#### 20.2 JUMPER SELECTION


#### **RS232**


Jumper g - installed for normal operation

**Jumper h** - installed when used as slave display

**Jumper j** - provides pull up resistor on RTS line

Shipped with jumpers q and j installed





#### **RS485**


Jumper g and j - add 121 ohm load resistors and are installed with long cables. If multiple meters are on same line, only the last meter in the line should be jumpered. **Jumper d** and **f** - installed for full duplex operation **Jumper c** and **e** - installed for half duplex operation Shipped with jumper d and f installed.

#### 21.

### **PARALLEL BCD OUTPUT**

#### 21. 1 OPERATING MODE MENU SELECTION

The following menu items are accessible only with a BCD option installed and appropriate lockouts enabled. See Section 9 for further information.



#### 21. 2 BCDOUTPUTLEVELS

The BCD option provides isolated, buffered, stored, 3-state parallel outputs that are selectable for either 0 to 5V logic levels (LSTTL, CMOS compatible) or 0 to 15Vdc. Selection jumpers are located on the BCD board. BCD outputs are positive true. Polarity bit is positive true for +sign.

LOGIC LEVEL	JUMPER REQUIRED
0 to 5Vdc	b
0 to 15Vdc	а

#### 21. 3 BCD CONTROL SIGNALS

Enable Logical 0 - All outputs go to the high impedance state

Logical 1 - BCD information is available at outputs.

BCD Hold Logical 0 - BCD from last update prior to BCD Hold going low is stored

Logical 1- BCD information updates at selected rate.

Data Ready Logical 0 - BCD outputs are valid

Logical 1 - BCD outputs are not valid

### 5, 10 AND 24 VDC EXCITATION OUTPUTS





Figure 22. 1 - Power Supply

### 22. 1 SELECTION OF 5, 10 OR 24VDC OUTPUT

Voltage Output	Jumper Locations
5 Vdc 10 Vdc	b, d and e b, d and f
24 Vdc	C



#### 22. 2 SELECTION OF OTHER JUMPERS

Jumper 'a ' - Front panel menu lockout, locked when installed (see Section 10.1)

Jumper ' **g** ' - Provides +5V power output at P1-4 when installed Jumper ' **h** ' - Connects "Digital Input B" to P1-4 when installed

#### 23.

#### **DIGITAL INPUTS**

#### 23.1 FUNCTION OF DIGITAL INPUTS

Tare Logical 1 - The displayed value is set to zero and stored as an offset value.

Logical 1 - The displayed value is equal to the signal input minus the tare value.

Peak Display Logical 0 - The peak value of the input signal is displayed.

Logical 1 - The present value of the input signal is displayed.

Hold Logical 0 - The meter display and outputs are held at the last reading.

Logical 1 - The display and outputs are updated normally

Reset Logical 0 - The microcomputer reads and resets the meter to nonvolatile memory values

Logical 1 - The meter display and outputs operate normally.

Function Reset Logical 0 - The microC resets peak to present value and resets alarms.

Logical 1 - The meter display and outputs operate normally.

External Decimal Points Input A Input B Decimal Pts 1 Decimal Pts 2

1 1 XXXXX XXXXX
0 1 XXXXXX XXXXXX
1 0 XXXXXX XXXXXX

0 0 XX.XX XX.XXX 0 0 XX.XXX X.XXXX

#### 23.3 MENUSELECTIONS

MENU KEY

**DIGIT SELECT KEY** 

**VALUE SELECT KEY** 



Press the key until SEtup (Basic meter setup) is displayed.



Press ▶ to display status.

Press ▶ again to select digit. Selected digit will flash.

Digit 5: digital inputs A & B at J1, Pins 5 and 4.



Press to select value for flashing digit

0 A: Reset B: Meter Hold

1 A: Function Reset B: Peak display

2 A: Meter Hold B: Peak

3 A: Meter Hold B: Tare

4 A: Peak B: Tare

5 A: Tare B: Reset 6 External Decimal Pts.1

7 External Decimal Pts.2

### 24. CALIBRATION

All ranges of the meter have been digitally calibrated at the factory prior to shipment. The calibration equipment is certified to NIST standards. Calibration constants are stored in non-volatile memory in EEPROM on the signal conditioner. This eliminates much of the analog circuitry that causes drift and provides superior long term accuracy and stability.

Since the calibration is stored on the signal conditioner and analog output boards, all boards may be mixed and interchanged without requiring recalibration. If recalibration is required, the meter may be returned to the factory or any authorized distributor.

For the customer requiring on site calibration, an RS-232 or RS-485 option must be installed to perform the calibration. The interface card may be temporarily installed and then removed upon completion of calibration. Step-by-step instructions for calibration and the equipment required is available from the factory.

25. SPECIFICATIONS

#### **BASIC METER**

#### **Display**

Type	5 LED, 7-segment,	14.2mm (.56	3") high d	digits	& 3 LEI	) in	dicators
Color					R	ed	or green
Range		99999 to	+99999	and	-99990	to	+99990

#### A to D Conversion

Technique (Pat.5,262,780)	Concurrent Slope™
Rate	60/s for 60 Hz NMR, 50/s for 50 Hz NMR
Output Update Rate	56/s at 60 Hz, 47/s at 50 Hz
Display Update Rate	

#### **Noise Rejection**

HzSafety-rated to 250Vac, 4.2kVp per High Voltag	e Test
Hz	30 dB
90 dB with minimum digital f	iltering

#### External Inputs/Outputs (CMOS/TTL Levels)

Hold input	0 - holds display and outputs
Peak input	0 - displays peak value
	0 - offsets input value to zero
	0 - resets all meter functions
Decimal Point input	

### **ACCURACY**

#### **DC Volts**

VOLTAGE	RESOLUTION	INPUT	ERROR
RANGE		OHMS	AT 25°C
200.00 mV 2.0000 V 20.000 V 200.00 V 660.0 V	10 uV 100 uV 1 mV 10 mV 100 mV	1 G 1 G 1 M 1 M 1 M	.01% Full Scale +/-2 Ct.

### **DC Amperes**

CURRENT	RESOLUTION	INPUT	ERROR
RANGE		OHMS	AT 25°C
2.0000 mA 20.000 mA 200.00 mA 5.000 A	0.1 uA 1.0 uA 10 uA 1.0 mA	100 10 1 .01	.01% Full Scale +/-2 Ct.

### Ratio

VOLTAGE	RESOLUTION	INPUT	ERROR
RANGE		OHMS	AT 25°C
200.00 mV	10 uV	1 G	.01% Full
2.0000 V	100 uV	1 G	Scale
20.000 V	1 mV	1 M	+/-2 Ct.

### True RMS Volts (1 to 100% Full Scale)

VOLTAGE	RESOLUTION	INPUT	ERROR
RANGE		OHMS	AT 25°C
200.00 mV 2.0000 V 20.000 V 200.00 V 660.0 V	10 uV 100 uV 1 mV 10 mV 100 mV	22 M 22M 1 M 1 M 1 M	.1% FS +/-10 Ct. from 10 Hz to 10kHz

### True RMS Amperes (1 to 100% Full Scale)

CURRENT	RESOLUTION	INPUT	ERROR
RANGE		OHMS	AT 25°C
2.0000 mA	0.1 uA	100	.1% FS
20.000 mA	1.0 uA	10	+/-10 Ct.
200.00 mA	10 uA	1	from 10 Hz
5.000A	.25 mA	.01	to 10kHz

### RTD's (.01, .1, 1.0 Degree Resolution)

PT100 TYPE	RANGE	ERROR AT 25°C
DIN	-202°C to +850°C	.01% FS +/- 0.03°C
.00385	-331°F to +1562°F	.01% FS +/- 0.05°F
ANSI	-202°C to +631°C	.01% FS +/- 0.04°C
.003925	-331°F to +1168°F	.01% FS +/- 0.07°F

### **Thermocouple**

### (.1, 1.0 Degree Resolution)

TC TYPE	RANGE	ERROR AT 25°C
J	-210°C to +760°C -347°F to +1400°F	.01% FS +/- 0.09°C .01% FS +/- 0.16°F
К	-244°C to +1372°C -408°F to +2501°F	.01% FS +/- 0.1°C .01% FS +/- 0.17°F
Т	0°C to +400°C -257°C to 0°C +32°F to 752°F -430°F to +32°F	.01% FS +/- 0.03°C .01% FS +/- 0.2°C .01% FS +/- 0.05°F .01% FS +/- 0.36°F
E	-240°C to +1000°C -400°F to +1830°F	.01% FS +/- 0.18°C .01% FS +/- 0.32°F
N	-244°C to +1372°C -408°F to +2501°F	.01% FS +/- 0.1°C .01% FS +/- 0.17°F
S	-46°C to +1768°C -51°F to +3213°F	.01% FS +/- 0.12°C .01% FS +/- 0.22°F
R	-45°C to +1768°C -49°F to +3214°F	.01% FS +/- 0.17°C .01% FS +/- 0.31°F

### **Load Cell Inputs**

INPUT RANGE	RESO- LUTION	ZERO	OUTPUT SPAN RANGE	ERROR AT 25°C
20.000 mV 50.000 mV 100.00 mV 250.00 mV 500.00 mV	1 uV 2.5 uV 5 uV 12.5 uV 25 uV	-99,999 to +99,999	0 to +/-99,999	.01%Full Scale +/-1Ct.

Load Cell Meter only Zero Tempco	
POWER SUPPLIES	
Input Voltage (opt) Frequency	
·	
	Safety-rated to 250Vac, 4.2kVp per High Voltage Test
DUAL CONTROLLER OPTION	I
Basic	
Update Rate	
Lockouts	Front panel pushbuttons control display and change of setpoints, only control display of setpoints, or are disabled.
·	either output may be set to operate above, below or ound the setpoint, latching or non-latching or output disabled
	comparison to the setpoints may be either from the filtered or unfiltered input signal
Time Delay	selectable time delay of output status change of 1 to 128 readings
Hysteresis	selectable from 0 to +/- 99,999 counts
Alarm Status Indicators Type	2 red LED lamps
Relay Output	

Isolation	
	Safety-rated to 250Vac, 4.2kVp per High Voltage Test
•	withstand 4.2kVp for 1 min26 ms typ.
Solid State Relay Output	
Voltage Rating	125Vac, 150 Vdc max.
	120 mAac, 240mAdc
Safety Certification	VDE, UL and CSA
	Safety-rated to 250Vac, 4.2kVp per High Voltage Test
Response to input signal	17 ms typ.
ANALOG OUTPUT OPTION	
	Safety-rated to 250Vac, 4.2kVp per High Voltage Test
	supplied by basic meter
	basic meter +/-0.1% Analog Full Scale for unfiltered input, same as basic meter for filtered input
Compliance	Tor drintered input, same as basic meter for intered input
•	12 V (0 to 600 Ohms)
	2 mA (5 kOhms min.) load
Scaling  Reading for Zero Output	00 000 to 100 000
· ·	99,999 to +99,999 
·	
RS-232 / RS-485 INTERFACE OP	TION
Isolation	Safety-rated to 250Vac, 4.2kVp per High Voltage Test
Power	supplied by basic meter
Type	full or half duplex (RS-485)
Olgridi Levels	Wicet No 232 and No 400 standards
BCD OUTPUT OPTION	
Isolation	Safety-rated to 250Vac, 4.2kVp per High Voltage Test
	supplied by basic meter
	3-state, stored, parallel
	LSTTL, CMOS compatible BCD Enable, Hold, Data Ready
Controls	Enable, Hold, Data Ready
ENVIRONMENTAL	
	0°C to 55°C
Storage Temperature	40°C to 85°C
Relative Humidity	90% from 0°C to 40°C

#### WARRANTY

UniMeasure meter products are warranted for one year from date of shipment against defects in materials and workmanship. During the warranty period, UniMeasure, at its option, will promptly repair or replace defective units at no charge to the purchaser if the product is returned to the factory freight prepaid. The warranty is void if the product is misused, damaged by accident, disassembled or intentionally abused. UniMeasure makes no other warranties either expressed or implied other than that above. UniMeasure assumes no liability for consequential damages under any circumstances. Prices, specifications and product appearance are subject to change without notice.